10. SCHEDULE 10: EQUIPMENT LIST

Transfer Date	LIMPO Site	-		
Transfer Date	HWRC Site	Equipment	Description Infrastructure - Sealed cess pit	Quantity
			with collar and inspection	
1st October 2009	Alconbury	CESS PITS	chamber.	1
1st October 2009	Alconbury	DRAINAGE	Infrastructure - Drains	23
1st October 2009	Alconbury	DRAINAGE	Infrastructure - Drain Covers	7
1st October 2009	Alconbury	HARD STANDING	Infrastructure - Approximately 726.52m ² - Tarmac roadway.	N/A
1st October 2009	Alconbury	HARD STANDING	Infrastructure - Approx 20 x 6.5m - Concrete paving underlying hazardous materials and fridges strorage area.	N/A
		TIVILE CITAING		IN/A
1st October 2009	Alconbury	HARD STANDING	Infrastructure - Approx 1330.8m ² - Sealed block paving area.	N/A
1st October 2009	Alconbury	HARD STANDING	Infrastructure - Approx 5 x 1m - Small concrete area	N/A
1st October 2009	Alconbury	INTERCEPTORS	3 chamber interceptor in good working order and recently cleaned. Annual skimming undertaken.	1
st October 2009	Alconbury	PERIMETER FENCING		
st October 2009	Alconbury	PORTAKABINS	Portakabin incorporating shower and toliet, sink, lighting and heating.	1
st October 2009	Alconbury	ROAD MARKINGS	Infrastructure - Ramp markings x 8, directional arrows x 8, central double white line along roadway, white parking lines x 2, speed hump markings x 4	N/A
st October 2009	Alconbury	SPEED HUMPS	Infrastructure - 4 x raised tarmac humps and two plastic speed ramps	6
st October 2009	Alconbury	WATER SUPPLY (Ext)	Infrastructure - Outside water point and tap. Hose affixed.	1
st October 2009	Alconbury	OFFICE & EQUIPMENT	Fixtures & Fittings, e.g. sinks, etc	
st October 2009	Alconbury	INFORMATIVE & INSTRUCTIONAL SIGNS	Signage - Various	20
st October 2009	Alconbury	SKIP SIGNS	Signage - Various	13
st October 2009	Alconbury	TRAFFIC SIGNS	Signage - Various	16
st October 2009	Alconbury	WARNING SIGNS	Signage - Various	4
st October 2009	Alconbury	CAGES	Waste Containers, etc - Cages - LPG cage with padlock. Galvanised steel.	1
st October 2009	Alconbury	CHEMVAULT	Waste containers, etc - Chemvault - Steel lidded unit used for the storage of batteries.	0
st October 2009	Alconbury	GANTRIES	Waste containers, etc - Gantries - 2 x long, 2 x short railed gantries. Waste conatiners - Lock & Leave	4
st October 2009	Alconbury		Containers - 6 x 2.4m Metal storage lockers used for storing valuables.	3

Was disposed of as was unfit for purpose.

	1		T	
			Waste containers, etc - Oil tanks	
			- Steel double skinned oil tank	
			with plagues attached indicating	
1st October 2009	Alconbury	OIL TANKS	no smoking and waste oil.	4
131 October 2003	Alconduty	OIL TAINS		
			Polypropylene stillage for storing hazardous waste. Lidded with	
1st October 2009	Alconbury	STILLAGES	padlock.	3
1st October 2009	Alconbury	FUSE BOXES	padiock.	
1st October 2009	Alconbury	KERBING	Office of the state of the stat	007
1st October 2009			3ft length kerb stones	297
TSt October 2009	Alconbury	KERBING	2ft length kerb stones	1160
			Infrastructure - Basic plastic gate to	
4-4-0-4-6	A 2 1		isolate interceptor from drainage	
1st October 2009	Alconbury	PENSTOCK	ditch.	1
		PREFAB CONCRETE	prefab concrete blocks skirting	
1st October 2009	Alconbury	BLOCKS	storage bays	31
			Brick wall with metal frame and	
			perspex upper sections.	
1st October 2009	Alconbury	SHELTER	Corrugated roofing	1
			Steps for old portakabin,	
1st October 2009	Alconbury	STEPS	redundant	1
1st October 2009	Alconbury	TRAFFIC GATES	Mesh fencing	2
			Standard sign poles used for	
			mounted entrance and traffic	
1st October 2009	Alconbury	SIGN POLES	signs	23
1st October 2009	Alconbury	CLOTHING BANK	10ft lock and leave	1

Transfer Date	HWRC Site	Equipment	Description	Quantity
			Infrastructure - Black painted bollards with white stripes. Located to prevent impact damage to	_
			platforms. One bollard located against wall (red). Purpose	00
1st October 2009	Bluntisham	BOLLARDS	unknown. Infrastructure - Type Unknown	28
1st October 2009	Bluntisham	CESS PITS		1
1st October 2009	Bluntisham	DRAINAGE	Infrastructure - Drains	11
			Infrastructure - Metallic box, sealed	
1st October 2009	Bluntisham	(EXT)	and locked. Near to lorry entrance.	1
13t October 2009	Diditionani	(LXI)	Infrastructure - Mezzanine platforms	
			with side railings, painted steel,	
1st October 2009	Bluntisham	FIXED PLATFORMS	providing skip access from upper level	14
St October 2009	Diulitisliaili	PIALD FLATTORNIS	Infrastructure - Flood lighting	
			comprising of 2 twins, 1 twin with a	
			spot, 11 single lights and 4 single	
			lights with a spot. All reportedly in	40
1st October 2009	Bluntisham	FLOOD LIGHTING	working order. Infrastructure - Isolation value	18
1st October 2009	Bluntisham	GATE VALUE		11
1-4-0-4-4	Divertishes	LIADD CTANDING	Infrastructure - Approx 4736m ²	N/A
1st October 2009	Bluntisham	HARD STANDING	Tarmac roadway / areas. Infrastructure - Approx 712.5m ² -	IN/A
			Concrete pads for waste storage	
			areas and RORO skips on lower	
1st October 2009	Bluntisham	HARD STANDING	level.	N/A
			Infrastructure - Approx 636m ² -	
			Sealed block weave paving for	
1st October 2009	Bluntisham	HARD STANDING	storage of recycables containers.	N/A
			Infrastructure - 3 chamber interceptor in good working order	
			and recently cleaned. Annual	
1st October 2009	Bluntisham	INTERCEPTORS	skimming undertaken.	1
			Infrastructure - 473m - Site boundary	
			kerbing. Standard kerb stones	
st October 2009	Bluntisham	KERBING	around perimeter. (Single Width)	N/A
			Infrastructure - Located to the rear	
			doesn't appear to be in use, positioned behind a lock and leave	
	ĺ		container. The gate is constructed	
			of the same steel palisade fencing	
st October 2009	Bluntisham	PEDESTRIAN GATES	used on the remainder of the perimeter.	1
131 OCIODEI 2009	Juntionalii	PERIMETER	Infrastructure - 345m - Steel	
1st October 2009	Bluntisham	FENCING	palisade fencing	N/A
			Infrastructure - 30 x 10 - 4 rooms.	
			Used as main office, complete with	
1st October 2009	Bluntisham	PORTAKABINS	toliet and shower.	1
			Infrastructure - Houed within metal	
st October 2009	Bluntisham	PUMPS	painted box with Yale lock.	1
131 October 2009	Diumonam	I OWF O	Infrastructure - 280m - Yellow	
			railings streching from lorry site	
			entrance to end of skip line (lower	
st October 2009	Bluntisham	RAILINGS	level)	N/A
	1		Infrastructure - Rasied tarmac	

		T-	L. Chad palicado gotos	
			Infrastructure - Steel palisade gates.	
	Divinitialisma	TDAFFIC CATES	Fairly new. Recently repaired following a break in.	3
1st October 2009	Bluntisham	TRAFFIC GATES	Infrastructure - Outside tap mounted	<u> </u>
			on wooden post to be used for	
1st October 2009	Bluntisham	WATER SUPPLY (ext)	damping down site when nesscary Miscellaneous - 336L - Yellow water	11
			proof containers used for the storage	
	Di districci	ROAD SALT	of road salts.	3
1st October 2009	Bluntisham	CONTAINER	Signage - Various	
4-4-0-4-1	Diuntiaham	INFORMATIVE & INSTRUCTIONAL ISIGNS	Signage - Valious	14
1st October 2009	Bluntisham	OFFICE &	Fixtures & Fittings - Various	
1st October 2009	Bluntisham	EQUIPMENT		8
1st October 2009	Bluntisham	SKIP SIGNS	Signage - Various	19
1st October 2009	Bluntisham	TRAFFIC SIGNS	Signage - Various	14
1st October 2009	Bluntisham	WARNING SIGNS	Signage - Various	14
			Waste containers, etc - Metal cages provided by the council for the storage of LPG cylinders.	
1st October 2009	Bluntisham	CAGES	Padlocked.	1
4-4-0-4-4	Bluntisham	CAGES	Waste containers, etc - Metal cages provided by the council for the storage of LPG cylinders. Padlocked. Will be moved to Thriplow when Thriplow is redeveloped	1
1st October 2009	Diuntisnam	UNGLO	Waste containers, etc - Steel lidded and sealed container for use in storing hazardous materials.	
1st October 2009	Bluntisham	CHEMVAULT	Lockable.	11
			Waste containers, etc - Wheeled	
1st October 2009	Bluntisham	GANTRIES	gantries (short) with rails.	4
1st October 2009	Bluntisham	LOCK AND LEAVE	Waste containers, etc - 6 x 2.4m - 20ft containers used for storing items of value.	5
			Waste containers, etc - Double skinned painted steel tank with filter mesh to ensure solids do not enter	
1st October 2009	Bluntisham	OIL TANKS	the tank.	1
			Polypropylene stillage for storing hazardous waste. Lidded with padlock.	
1st October 2009	Bluntisham	STILLAGES	, , , , , , , , , , , , , , , , , , , ,	2
1st October 2009	Bluntisham	DRAIN COVERS		9
1st October 2009	Bluntisham	PREFAB CONCRETE BLOCKS	Storage area for domestic appliances	41
			Traffic road markings including arrows to Indicate direction of flow and 4 marked parking bays. Yellow line marking skip positioning and accompanying hatch markings.	
1st October 2009	Bluntisham	ROAD MARKINGS	Set of 2 metal steps designed for	
1st October 2009	Bluntisham	STEPS	portakabin Standard poles for supporting traffic	11
1st October 2009	Bluntisham	SIGN POLES	signs	24

Transfer Date	HWRC Site	Equipment	Description	Quantity
1st October 2009	Grunty Fen	CESS PITS	Infrastructure - Sealed cess pit with collar and inspection chamber.	1
	Grunty Fen	DRAINAGE	Infrastructure - Drainage tank. Steel, sealed. Used for storing site water prior to discharge / removal.	1
		DRAINAGE	Infrastructure - Approx site area 2000m ² - Drains.	1
1st October 2009	Grunty Fen	HARD STANDING	Infrastructure - Approx 2000m ² - Site laid to tarmac.	N/A
1st October 2009	Grunty Fen		Infrastructure - Chain link gates.	1
1st October 2009	Grunty Fen	PERIMETER	Infrastructure - 157m - Concrete posts with chain link fencing. Runs around perimeter although HWRC site is only responsible for fencing along the western, northern boundaries and the entrance gates. The landfill site takes responsibility for the Eastern most boundary of the site.	
1st October 2009	Grunty Fen	FENCING	Infrastructure - Office building, complete with shower and toilet	N/A
1st October 2009	Grunty Fen	PORTAKABINS	facilities. 4 rooms. Infrastructure - Pump for	1
1st October 2009	Grunty Fen	PUMPS	drainage system, installed Jan/Feb 04, with new pipework. Infrastructure - White lining of	1
1st October 2009	Grunty Fen	ROAD MARKINGS	roadway and Skip line markings	N/A
1st October 2009		STEEL FIXINGS	Infrastructure - Approx 2.5m long - Floor mounted steel fixings / wheel stops to protect drainage pipework from skip movements.	8
1st October 2009	Grunty Fen	STEPS	Infrastructure - 3 steps with railings to allow entry to the portakabin. Came with Cabin. Metal.	1
1st October 2009	Grunty Fen	STEPS	Infrastructure - Concrete step up to oil tank. Covered with rubber mat.	1
1st October 2009	Grunty Fen	TRAFFIC GATES	Infrastructure - Chain link gates.	1
1st October 2009	Grunty Fen	ROAD SALT CONTAINER	Miscellaneous - 336l - Yellow lidded road salt container. Plastic.	1
1st October 2009	Grunty Fen	INFORMATIVE & INSTRUCTIVE SIGNS	Signage - Various	25
1st October 2009	Grunty Fen	SKIP SIGNS	Signage - Various	8
1st October 2009	Grunty Fen	TRAFFIC SIGNS	Signage - Various	5
1st October 2009	Grunty Fen	WARNING SIGNS	Signage - Various	10
1st October 2009	Grunty Fen	CAGES	Waste containers, etc - LPG cage with padlock. Galvanised steel. Waste containers, etc - Portastor Chemvault. Steel	1
1st October 2009	Grunty Fen	CHEMVAULT	lockable container used for the storage of batteries.	1 1
1st October 2009	Grunty Fen	LOCK & LEAVE CONTAINERS	Waste containers, etc - 20ft metal lock and leave container.	3

1st October 2009	Grunty Fen	LOCK & LEAVE	Waste containers, etc - 20ft metal lock and leave container used for the storage of textiles.	0
	Grunty Fen	LOCK & LEAVE CONTAINERS	Waste containers, etc - Portastor lock and leave (metal).	0
1st October 2009		OIL TANKS	Waste containers, etc - Double skinned steel tank.	11
1st October 2009	Grunty Fen	STILLAGES	Polypropylene stillage for storing hazardous waste. Lidded with padlock.	3
1st October 2009	Grunty Fen	PREFAB CONCRETE BLOCKS	Blocks have been relocated since the changes at the site and have incurred some damage.	11
1st October 2009	Grunty Fen	SAND BAGS	Sand bagging up to about 1m in height around Northern and Western boundaries of the site.	N/A
1st October 2009	Grunty Fen	SIGN POLES	Standard sign poles used for mounted entrance and traffic signs.	3
1st October 2009	Grunty Fen	OFFICE & EQUIPMENT	Fixture & fittings - Various	8

	I			
Transfer Date	HWRC Site	Equipment	Description Infrastructure - Sealed cess pit with collar	Quantity
1st October 2009	March	CESS PITS	Infrastructure - Sealed cess pit with collar and inspection chamber.	1
	March	DRAINAGE	Infrastructure - Drains.	8
1st October 2009		FLOOD LIGHTING	Infrastructure	8
1st October 2009	March	PLOOD LIGHTING	Infrastructure - Approx 2457m ² - Tarmac	
•			roadway. Skip lorry area also laid to	N/A
1st October 2009	March	HARD STANDING	tarmac. Infrastructure - Approx 210m² - Sealed	IV/A
			block paying to centre of site. Also in skip	
			storage areas at southern and northern sides of site.	N 1/0
1st October 2009	March	HARD STANDING	Infrastructure - Approx 1.2m x 0.75m -	N/A
1st October 2009	March	HARD STANDING	Concrete paving at rear gate.	N/A
150 000000, 2000			Infrastructure - 3 chamber interceptor in good working order. Annual skimming	
			undertaken.	1 1
1st October 2009	March	INTERCEPTORS	Infrastructure - 3ft long kerb stones -	
			Kerbing around the perimeter. Also a few	
		KEDDING	corner kerb stones in good condition.	Approx 185
1st October 2009	March	KERBING	Infrastructure - Steel palisade gate to rear	
1st October 2009	March	PEDESTRIAN GATES	of site, behind PK.	1
13t October 2000			Infrastructure - Basic plastic gate to isolate	
1st October 2009	March	PENSTOCK	interceptor from drainage ditch.	11
		PERIMETER	Infrastructure - Approx 182m - Steel palisade fencing.	N/A
1st October 2009	March	FENCING	Infrastructure - Comprising of toilet and	IN/A
1st October 2009	March	PORTAKABINS	office area.	11
		CONCRETE	Infrastructure - Prefab concrete blocks skirting storage bays.	38
1st October 2009	March	BLOCKS	Infrastructure - No entry and give way	
			markings; traffic direction arrows x 5; Solid	
			white line marking roadway boundary; Dashed line marking parking zone; Speed	
			humps arrow markings; IN lettering.	
1st October 2009	March	ROAD MARKINGS	Infrastructure - Raised tarmac speed	N/A
4-1-0-4-5	March	SPEED HUMPS	humps.	4
1st October 2009	March	GFEED HOW 3	Infrastructure - 3 sets of steel palisade	
1st October 2009	March	TRAFFIC GATES	gates. Miscellaneous - Yellow plastic container to	3
		ROAD SALT	keep road salts free from moisture.	
1st October 2009	March	CONTAINER		2
		OFFICE &	Fixture & fittings - Various	
1st October 2009	March	EQUIPMENT	Signage - Various	6
		INFORMATIVE & INSTRUCTIVE	Signage - Various	
1st October 2009	March	SIGNS		18
1st October 2009	March	SKIP SIGNS	Signage - Various	14
1st October 2009	March	TRAFFIC SIGNS	Signage - Various	13
1st October 2009	March	WARNING SIGNS	Signage - Various	3
Tat October 2009	14101011	TW. WALLES CHOOL	Waste containers, etc - Old battery box,	
1st October 2009	March	BATTERY BOXES	used to store absorbent sacks.	1
13t October 2009	INGION	D. T. PERT BOXES	Waste containers, etc - LPG cage with	
	March	CACES	padlock. Galvanised steel.	1
1st October 2009	March	CAGES	Waste containers, etc - Steel painted	
			lockable container. Lidded.	4
1st October 2009	March	CHEMVAULT	Waste containers, etc - Metal storage	11
		LOCK & LEAVE	lockers used for storing valuables.	4
1st October 2009	March	CONTAINERS		

			Waste containers, etc - Double skinned oil tank with mesh catch all.	
4-4-0-4-6-2000	March	OIL TANKS		1
1st October 2009	Watch	7,2	Polypropylene stillage for storing	
			hazardous waste. Lidded with padlock.	3
1st October 2009	March	STILLAGES		
	March	SIGN POLES	Standard sign poles used for mounted entrance and traffic signs.	10
1st October 2009	IVIAICII	0.000	Stand alone shower cubicle, plumbing etc	
1st October 2009	March	SHOWER		11

Transfer Date	HWRC Site	Equipment	Description	Quantity
1st October 2009	Milton	CESS PITS	Infrastructure - Accepts drainage from welfare areas.	1
1st October 2009	Milton	DRAINAGE	Infrastructure - Approx 505m ² - Drains.	23
1st October 2009	Milton	DRAINAGE	Infrastructure - Drain covers	4
1st October 2009	Milton	ELECTRICAL BOXES (EXT)	Infrastructure - 1 Containing 3 sockets, the other providing power for PK1 & 2.	2
			Infrastructure - 4 x 2 bulb lights and 2 x 1 bulb lights at the Nth and Sth perimeter of the site.	6
1st October 2009	Milton	FLOOD LIGHTING	Infrastructure - Approx 460m ² -	6
1st October 2009	Milton	HARD STANDING	Tarmac Roadway	N/A
1st October 2009	Milton	HARD STANDING	Infrastructure - Approx 4544.95m ² - Steel reinforced concrete	N/A
1st October 2009	Milton	HEIGHT RESTRICTION BARRIERS	Infrastructure - Poles in place but height bar removed and placed on grassed area.	1
1st October 2009	Milton	INTERCEPTORS	Infrastructure - 3 chamber interceptor in good working order and recently cleaned. Annual skimming undertaken.	1
			Infrastructure - Kerbing for haz compound. 2 kerb stones wide area bunding oil stores. Stones sunken into concrete hard standing	
1st October 2009	Milton	KERBING	Infrastructure - Single width kerbing	N/A
1st October 2009	Milton	KERBING	around entire site.	N/A
1st October 2009	Milton	PEDESTRIAN GATES	Infrastructure - 2 x 1.8m - Galvanized chain link gate.	1
1st October 2009	Milton	PERIMETER FENCING	Infrastructure - Galvanized chain link	1
1st October 2009	Milton	PORTAKABINS	Infrastructure - Office building, complete with shower and toilet facilities. 4 rooms. On brick stilts.	1
	Milton	PREFAB CONCRETE BLOCKS	Infrastructure - Used to create segregation areas for electronic goods and bordering site perimeter around new office. (west end)	77
1st October 2009	Milton	ROAD MARKINGS	Infrastructure - Arrows marking traffic flow and marked spaces for parking. Yellow line marking skip positioning, south side of site. Ramp lettering. Intermittent lining in white. Extra yellow lines for rubbish skip bays. Triangle in white thermoplastic.	N/A
1st October 2009	Milton	SPEED HUMPS	Infrastructure - Raised tarmac	
1st October 2009	Milton	STEPS	Infrastructure - 2 level steps	4
1st October 2009			constructed for access to PK2. 2 course brick and paved.	1
1st October 2009	Milton	TRAFFIC GATES	Infrastructure - Galvanized chain link gates.	3
.5. 00.000. 2003	Milton	WATER SUPPLY (Ext)	Infrastructure - Outside tap mounted on wooden post to be used for	
1st October 2009	Milton	BARRIER	damping down site when necessary. Miscellaneous - Metal framed barriers	1
1st October 2009			with high vis banding used for restricting public access to skips.	0

	Milton	ROAD SALT	Miscellaneous - 336l - Plastic lidded	
		CONTAINER	containers for the storage of road	
1st October 2009			salts.	3
	Milton	INFORMATIVE &		
1st October 2009		INSTRUCTIVE	Signage - Various	26
1st October 2009	Milton	SKIP SIGNS	Signage - Various	25
1st October 2009	Milton	TRAFFIC SIGNS	Signage - Various	. 17
1st October 2009	Milton	WARNING SIGNS	Signage - Various	7
	Milton	BATTERY BOXES	Dual compartment battery storage boxes. Wooden and containing drainage holes. Not in use. No padlocks.	
1st October 2009	<u> </u>			0
1st October 2009	Milton	CAGES	Metal cages used for storing LPG cylinders, with padlocks.	2
1st October 2009	Milton	CHEMVAULT	Metal locked container used for haz material storage. (Portastor)	1
1st October 2009	Milton	LOCK & LEAVE CONTAINERS	Used specifically for electrical goods. Steel container. 12M X 2.4 M	1
1st October 2009	Milton	LOCK & LEAVE CONTAINERS	Variously used for valued goods. 6M X 2.4 M	5
	Milton	OIL TANKS	Double skinned oil tank with mesh	
1st October 2009			catch all.	1
	Milton		Polypropylene stillage for storing hazardous waste. Lidded with padlock.	
1st October 2009		STILLAGES		3
1st October 2009	Milton	FUSE BOXES		11
1st October 2009	Milton	SIGN POLES	Poles for signage at entrance to site	12

Transfer Date	HWRC Site	Equipment	Description	Quantity
1st October 2009	St Neots	DRAINAGE	Infrastructure - Approx 2418m² - Drains.	8
	St Neots		Infrastructure - Metal drain covers.	7
1st October 2009	St Neots	ELECTRICAL BOXES	Infrastrcuture - Located at the northern perimeter of the site, the box is galvanized metal with inbuilt lock.	1
TSI October 2003	Of Hoots		Infrastructure - 18m x 10m, 22m x 7.7m, 15m x 7.5m - Concrete pads for waste storage areas. Pavement quality concrete min 100mm thick with 2002 additions min 250mm thick	
1st October 2009	St Neots	HARD STANDING	2	N/A
1st October 2009	St Neots	HARD STANDING	Infrastructure - Approx 1956.1m ² - Tarmac roadway. Infrastructure - SPEL series 100, Model 102 with	N/A
4 - 1 0 - 1 - 1 - 2000	Ct Nooto	INTERCEPTORS	360 litre silt capacity. Class 1 separator.	1
1st October 2009	St Neots		Infrastructure - Standard 3ft kerb stones around the entire perimeter (excluding end area not currently available for use)	N/A
1st October 2009	St Neots	KERBING	Infrastructure - Steel framed with chain link.	1
1st October 2009	St Neots	PEDESTRIAN GATES	Infrastructure - Isolates interceptor, preventing	
4-1-0-1-10000	St Noote	PENSTOCK	discharge.	1
1st October 2009	St Neots	PENSTUCK	Infrastructure - Approx 162m palisade fencing - Steel palisade fencing (2.4m) along the rear boundary (east) with planking (approx 250) to obscure vision into the site. Along the Nth perimeter of the site stands a boundary wall (2.5m) The southern boundary is marked by steel palisade fencing, with some standard chain link fencing still in place as this meets the rear	
1st October 2009	St Neots	PERIMETER FENCING	boundary.	N/A
			Infrastructure - 20ft complete with shower and toilet facilities and in good condition.	1
1st October 2009 1st October 2009	St Neots	PORTAKABINS ROAD MARKINGS	Infrastructure - Arrows on speed hump. Centre road line. Centre road markings. Give way lines. Parking spaces (19) and yellow cross hatching at the centre of the site.	
	St Neots	SPEED HUMPS	Infrastructure - Raised tarmac humps for traffic control, with markings indicating direction of travel.	1
1st October 2009	St Neots		Infrastructure - Set of entrance gates. Steel, topped with barbed wire, served by 2 padlocks.	1
1st October 2009	St Neots	TRAFFIC GATES	Infrastructure - Outside tap in serviceable condition. Used for damping down etc.	1
1st October 2009	St Neots St Neots	ROAD SALT	Miscellaneous - 336l - Yellow lidded road salt container.	1
1st October 2009	OC MEDIS	OUTTAINEN	Fixture & fittings - Various	
1st October 2009	St Neots	OFFICE & EQUIPMENT		9
1st October 2009	St Neots	INFORMATIVE & INSTRUCTIVE SIGNS	Signage - Various	16
1st October 2009	St Neots	WARNING SIGNS	Signage - Various	3
1st October 2009	St Neots	SKIP SIGNS	Signage - Various	12
1st October 2009	St Neots	CAGES	Waste containers, etc - Metal cages used for storing LPG cylinders, with padlocks.	1
1st October 2009	St Neots	GANTRIES	Waste containers, etc - Metal wheeled gantries for skip access.	2
1st October 2009	St Neots	LOCK & LEAVE	Waste containers, etc - Metal containers with concealed locks, for the containment of valuable or salvageable items. Waste containers, etc - 20ft metal lock and leave	1
1st October 2009	St Neots	LOCK & LEAVE CONTAINERS	container.	2

1st October 2009	St Neots	OIL TANKS	Waste containers, etc - Double skinned painted steel tank with filter mesh to ensure solids do not enter the tank.	1
1st October 2009	St Neots	STILLAGES	Polypropylene stillage for storing hazardous waste. Lidded with padlock.	3
1st October 2009		TEXTILE BANK	20ft Lock and Leave with side access	1

	HWRC Site	Equipment		0
Transfer Date			Description Infrastructure - Sealed cess pit with	Quantity
1st October 2009	Thriplow	CESS PITS	collar and inspection chamber.	1
1st October 2009	Thriplow	DRAINAGE	Infrastructure - Approx 3196m ² - Drains.	25
1st October 2009	Thriplow	DRAINAGE	Infrastructure - Drain covers	6
130 0000001 2000	TimpleW	- DIVINGE	Infrastructure - Drainage channel	
1st October 2009	Thriplow	DRAINAGE	grate (like aco drainage).	1
		ELECTRICAL		
1st October 2009	Thriplow	BOXES (EXT)	Infrastructure	1
1st October 2009	Thriplow	FLOOD LIGHTING	Infrastructure	6
1st October 2009	Thriplow	GATE VALVE	Infrastructure	1
4 . 0		LIADD OTANDINO	Infrastructure - Aprrox 412.4m² - Concrete pads underlying oil tank, battery compound and recycling bins.	N/A
1st October 2009	Thriplow	HARD STANDING	Infrastructure - Approx 929.9m ² -	N/A
1st October 2009	Thriplow	HARD STANDING	Tarmac roadway.	N/A
			Infrastructure - 1086.4m ² - Sealed block paving for waste storage areas,	
1st October 2009	Thriplow	HARD STANDING	central storage area.	N/A
13t October 2003	Timplov	TIAND OTANDING	Infrastructure - Metal barrier	11//
1st October 2009	Thriplow	HEIGHT RESTRICTION BARRIERS	supported by 2 uprights. Barrier no longer in place as it caused an obstruction to the collection of waste fridges / freezers.	1
			Infrastructure - 3 chamber interceptor in good working order and recently cleaned. Annual skimming	
1st October 2009	Thriplow	INTERCEPTORS	undertaken.	1
1st October 2009	Thriplow	KERBING	Infrastructure - Standard 3ft kerb stones around the entire perimeter (excluding end area not currently available for use)	N/A
			Infrastructure - Skirting concrete pads underlying oil / batteries and LPG storage area. Double thickness along sides of oil tank. Single kerbing	
1st October 2009	Thriplow	KERBING	around glass recycling bins.	N/A
		PERIMETER	Infrastructure - Approx 232m - Corrugated metal sheet fencing borders the site from the northern most tip to the southern most edge of the site. The remainder of the site is	
1st October 2009	Thriplow	FENCING	enclosed by chain link fencing. Infrastructure - 30ft x 10ft - Portakabin installed Nov 04. Electrical checks conducted upon installation. Complete with shower and toilet.	N/A
1st October 2009	Thriplow	PORTAKABINS		1
		PREFAB	Infrastructure - Concrete blocks	
1st October 2009	Thriplow	CONCRETE BLOCKS	skirting fridge storage area.	30
Ist October 2009	Thriplow	ROAD MARKINGS	Infrastructure - Markings indicating GW x3, 4 x RAMP, HH x2, 9 x directional arrows, Solid white lining for roadway, Parking bays. Arrows on speed humps. Triangle in white thermoplastic.	N/A
	<u> </u>		Infrastructure - Raised tarmac	

			Infrastructure - 2 sets of galvanised	
			steel framed gates, chain link. With	
1st October 2009	Thriplow	TRAFFIC GATES	padlocks.	2
		WATER SUPPLY	Infrastructure - Outside water point	
1st October 2009	Thriplow	(Ext)	and tap. Hose affixed.	1
			Miscellaneous - 336l - Yellow plastic	
		ROAD SALT	container to keep road salts free from	
1st October 2009	Thriplow	CONTAINER	moisture.	1
		OFFICE &	Fixture & Fittings - Various	
1st October 2009	Thriplow	EQUIPMENT	_	7
130 0000001 2000	Timplow	INSTRUCTIVE &	Signage - Various	·
		INFORMATIVE	Cignage various	
1st October 2009	Thriplow	SIGNS		21
			Signage - Various	
1st October 2009	Thriplow	SKIP SIGNS	0 0	14
1st October 2009	Thriplow	TRAFFIC SIGNS	Signage - Various	3
1st October 2009	Thriplow	WARNING SIGNS	Signage - Various	4
			Waste containers, etc - Galvanised	
			steel LPG cage with padlock.	
1st October 2009	Thriplow	CAGES		1
			Waste containers, etc - Short gantry	
1st October 2009	Thriplow	GANTRIES	with railing.	1
		LOCK & LEAVE	Waste containers, etc - Metal 20ft	
1st October 2009	Thriplow	CONTAINERS	lock and leave containers.	4
131 0010001 2000	Trinplow	JOONTANIENO	Waste conatiners, etc - Double	•
1st October 2009	Thriplow	OIL TANKS	skinned oil tank with mesh catch all.	1
151 October 2009	THIDIOW	IOIL IVINO	Polypropylene stillage for storing	
			hazardous waste. Lidded with padlock.	
1st October 2009	Thriplow	STILLAGES	The state of the s	3
	1		One set of metal steps with railings	
			designed to attach to portakabin to allow	
1st October 2009	Thriplow	STEPS	easy access.	1
		SIGN POLES	Standard sign poles used for mounted	
1st October 2009	Thriplow		entrance and traffic signs.	15

	HWRC Site	Equipment		
Transfer Date			Description	Quantity
1at Oatabar 2000	Whittlesey	DRAINAGE	Infrastructure - One drain - only one on site.	1
1st October 2009	VVIIItlesey	ELECTRICAL	Infrastructure - Metal box encasing	
1st October 2009	Whittlesey	BOXES (EXT)	electricity boards etc.	1
4 . 0 . 1 . 0000			Infrastructure - Lighting for use in	4
1st October 2009	Whittlesey	FLOOD LIGHTING	failing light. Not currently used. Infrastructure - Tarmac estimated as	4
			covering approx 3/4 of the site,	
			1434.38m ² . Concrete covers 1/4 of the	
			site 478.13m ^{2.} Site laid to tarmac	
			except in household waste storage	
1st October 2009	Whittlesey	HARD STANDING	areas, which consist of concrete pads	N/A
1st October 2009	VVIIIttlesey	TIAND STANDING	(sealed). Infrastructure - Drainage gulley along	1477
			both lengths of the central concrete	
			area, serving the are for the storage of	
1 = 1 O = 1 = 1 = 2000	\ \	HARD CTANDING	household and green wastes.	N/A
1st October 2009	Whittlesey	HARD STANDING	Infrastructure - 3 chamber interceptor	14//
			in good working order and recently	
			cleaned. Annual skimming	
1st October 2009	Whittlesey	INTERCEPTORS	undertaken.	1
			Infrastructure - Approx 181.25m - Steel palisade fencing topped with 3	
			rows of barbed wire to raise to 2.4	
			metres. Green due to adjacent nature	
		PERIMETER	reserve. Installed approximately 1	
1st October 2009	Whittlesey	FENCING	year ago. Covers entire site perimeter.	N/A
			Infrastructure - Portakabin installed Feb 2000. In good condition.	
			Functional shower and toilet.	
1st October 2009	Whittlesey	PORTAKABINS	Defel	11
		PREFAB CONCRETE	Infrastructure - Prefab concrete blocks skirting storage bays.	
1st October 2009	Whittlesey	BLOCKS	John Ling Storage Daye.	24
			Infrastructure - Entrance arrows / exit	
			arrows. Roadway lining, skip line	
	-		markings, material indicators (i.e. household, GW). Keep road clear and	
			no entry / danger / keep out markings	
			(behind skips).	
1st October 2009	Whittlesey	ROAD MARKINGS		N/A
			Infrastructure - 2 sets of steel palisade	İ
	l		gates, with padlocks.	_
1st October 2009	Whittlesey	TRAFFIC GATES	Fixture & Fittings - Various	2
1st October 2009	Whittlesey	OFFICE & FOLLIDA		9
13t October 2009	vinuesey	OFFICE & EQUIPM	Signage - Various	
		INSTRUCTIVE &		
1st October 2009	Whittlesey	INFORMATIVE SIGNS		20
131 0010081 2009	VVIIILLIESEY	JOIGINO	Signage - Various	
1st October 2009	Whittlesey	SKIP SIGNS		16
1st October 2009	Whittlesey	TRAFFIC SIGNS	Signage - Various	3
			Signage - Various	5
1st October 2009	Whittlesey	WARNING SIGNS	Waste containers, etc - LPG cage	· ·
1st October 2009	Whittlesey	CAGES	with padlock. Galvanised steel.	1
13t October 2009	vintiesey		Waste Containers, etc - Portstor	F.
1st October 2009	Whittlesey	CHEMVAULT	chemvault. Steel container.	1
	1	LOCK & LEAVE	Waste Containers, etc - Metal	
1st October 2009	Whittlesey	CONTAINERS	lockable storage containers.	3
			Waset Containers, etc - Double	
1st October 2009	Whittlesey	OIL TANKS	skinned oil tank with mesh catch all.	1
131 001000 2009	Tanumeseà	TOIL IMINO	<u> </u>	

			Polypropylene stillage for storing hazardous waste. Lidded with padlock.	
1st October 2009	Whittlesey	STILLAGES		3
		SIGN POLES	Standard sign poles used for mounted	
1st October 2009	Whittlesey		entrance and traffic signs.	6
1st October 2009	Whittlesey	FUSE BOX		1

Transfer Date	HWRC Site	Equipment	Description	Quantity
1st October 2009	Wisbech	FLOOD LIGHTING	Infrastructure - Lighting for use in failing light. Not currently used.	2
			Infrastructure - Approx 798m ² - Tarmac roadway.	
1st October 2009	Wisbech	HARD STANDING	Infrastructure - Approx 2140.4m ² - Sealed block paving to centre of site and skirting tarmac	N/A
1st October 2009	Wisbech	HARD STANDING	roadway.	N/A
1st October 2009	Wisbech	HARD STANDING	Infrastructure - 117ft Long - Concrete gulley	N/A
1st October 2009	Wisbech	HARD STANDING	Infrastructure - 219m ² - Concrete paving underlying fridge storage area.	N/A
1st October 2009	Wisbech	HARD STANDING	Infrastructure - 3.03m x 3.03m - Concrete pad for bund	N/A
1st October 2009	Wisbech	HARD STANDING	Infrastructure - 1.67 x 2.57 m -Concrete area underlying battery storage area.	N/A
1st October 2009	Wisbech	HEIGHT RESTRICTION BARRIERS	Infrastructure - Metal barrier supported by 2 uprights.	1
1st October 2009	Wisbech	INTERCEPTORS	Infrastructure - 3 chamber interceptor in good working order and recently cleaned. Annual skimming undertaken.	1
1st October 2009	Wisbech	KERBING	Infrastructure - 373 ft - Kerbing around the perimeter and central paved area. Kerbing	N/A
1st October 2009	Wisbech	PERIMETER FENCING	Infrastructure - Approx 207m - Steel palisade fencing skirting entire perimeter.	N/A
st October 2009	Wisbech	PORTAKABINS	Infrastructure - Brick built office. Complete with shower and toilet.	1
st October 2009	Wisbech	PREFAB CONCRETE BLOCKS	Infrastructure - Concrete blocks skirting storage bays. 27 @ 2m high and 18 @ 1m high.	45
Ist October 2009	Wisbech	ROAD MARKINGS	Infrastructure - Markings indicating, No entry, give way lines, central road markings, 6 x directional arrows, 2 x GW, 2 x HW, Entry, Speed hump arrows, Hatch markings for bend.	N/A
1st October 2009	Wisbech	SPEED HUMPS	Infrastructure - Raised tarmac speed humps.	6
st October 2009	Wisbech	TRAFFIC GATES	Infrastructure - 2 sets of entrance gates. Steel palisade.	2
st October 2009	Wisbech	ROAD SALT CONTAINER	Miscellaneous - Yellow plastic container to keep road salts free from moisture.	1
st October 2009	Wisbech	OFFICE & EQUIPMENT	Fixture & Fittings - Various	1
st October 2009	Wisbech	INSTRUCTIVE & INFORMA	Siganage - Various	23
st October 2009	Wisbech	SKIP SIGNS	Signage - Various	15
st October 2009	Wisbech	TRAFFIC SIGNS	Signage - Various	18
st October 2009	Wisbech	WARNING SIGNS	Signage - Various	5
st October 2009	Wisbech	CAGES	Waste Containers, etc - LPG cage with padlock. Galvanised steel.	1
st October 2009	Wisbech	LOCK & LEAVE CONTAINERS	Variously used for valued goods. 6M X 2.4 M Two containers have internal electrics.	4
st October 2009	Wisbech	OIL TANKS	Waste containers, etc - Metal double skinned oil storage tank.	· 1
st October 2009	Wisbech	STILLAGES	Polypropylene stillage for storing hazardous waste. Lidded with padlock.	3
st October 2009	Wisbech	LOCK & LEAVE CONTAINERS	Used specifically for electrical goods. Has internal electrics. Steel container. 12M X 2.4 M	1
st October 2009	Wisbech	SIGN POLES	Standard sign poles used for mounted entrance and traffic signs.	14
st October 2009 st October 2009	Wisbech Wisbech	DRAINAGE FUSE BOX	Infrastructure, Approximate site area is 3157.4 m2	21 1
st October 2009 st October 2009	Wisbech Wisbech		Infrastructure; steps up to office door, brick built and paved (3) External tap with hose connection.	1

Schedule 10 - Part 2 - Additional equipment from Donarbon.

HWRC Site	Equipment	Description	Quantity
		•	
All Sites	40YD RORO	Waste containers, etc	130 in total, to
		- Large metal	,
		container with a single	be split between
		door at one end.	
		 X-X	all of the Sites.
All Sites	12YD RORO	Waste containers, etc	22 in total, to be
		- Low sided metal containers for soil /	calit botwood all
		hardcore. Light green	split between all
		in colour.	of the Sites.
All Sites	GANTRIES	Waste containers, etc	60 in total, to be
•			split between all
			of the Sites
Alconbury	PORTAKABIN	Infrastructure	1
Bluntisham	PORTAKABIN	Infrastructure	1
Grunty Fen	PORTAKABIN	Infrastructure	1
March	PORTAKABIN	Infrastructure	1
Milton	PORTAKABIN	Infrastructure	1
St Neots	PORTAKABIN	Infrastructure	1
Thriplow	PORTAKABIN	Infrastructure	1
Whittlesey	PORTAKABIN	Infrastructure	1